

## BELZONA PROTECTS RISERS

### CUSTOMER

Offshore gas production platform

### APPLICATION DATE

July 2016

### APPLICATION SITUATION

Severe sorrosion on gas offshore platform risers

### PROBLEM

Damage to coating protection led to severe corrosion.

### PRODUCTS

Belzona 5831 (ST-Barrier)

### SUBSTRATE

Carbon steel

### APPLICATION METHOD

Application was carried out using a modified version of Belzona Know-How System Leaflet SOS-21.

### BELZONA FACTS

Belzona 5831 provides excelent adhesion on wet and minimal prepared surface and that fact makes this protection a very cost effective solution.

### PICTURES

1. Severe corrosion
2. Surface preparation
3. Application in progress
4. Finished aplication



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

