

BELZONA REBUILDS CRACKED WATER CHANNELS AT OUTDOOR POOL

CUSTOMER

Coquitlam, BC

APPLICATION DATE

April 2015

APPLICATION SITUATION

The water channel at outdoor pool.

PROBLEM

The pool gutter system had developed major cracks in various areas allowing water to escape.

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1

BELZONA FACTS

This was part of major refurbishment project to rehabilitate this outdoor swimming pool. A previous similar project had performed extremely well with no maintenance problems over the a period of 5 years.

PICTURES

1. Extent of cracks needing rebuilding
2. Surface preparation underway using a hand grinder to clean and remove all loose material
3. A completed section of repair
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2020


BELZONA
Repair • Protect • Improve