

BELZONA HELPS IN THE PROTECTION OF A SURFACE UNDER THE GRANULE SCRAPER.

CUSTOMER

Puławy, Poland

APPLICATION DATE

2019

APPLICATION SITUATION

Modernisation and protection of the surface area under the granule scraper.

PROBLEM

Corrosion of concrete and surface due to the scraper moving the granules around the area.

PRODUCTS

Belzona 4151 (Magma Quartz Resin)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

APPLICATION METHOD

Repair any surface damaged concrete areas with Belzona 4151 Sealing the surface under the scraper using Belzona 5811.

BELZONA FACTS

Long-lasting chemical resistance with Belzona 5811 securing the surface under the scraper.

PICTURES

1. Application Area Picture
2. Area to be treated under the scraper
3. Applying Belzona 4151 & Belzona 5811
4. Application Completed



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve