

PHARMACEUTICAL PLANT USES BELZONA SAFETY GRIP SYSTEM

CUSTOMER
Switzerland

APPLICATION DATE
May 2020

APPLICATION SITUATION
The client required a form of grip system for exterior use to stop any potential accidents or problems.

PROBLEM
The exterior flooring was an issue when the Pharmaceutical Plant forklift trucks were operating outside, causing the forklifts to slip when loading and un-loading.

PRODUCTS
Belzona 4111 (Magma Quartz)
Belzona 5231 (SG Laminate)
Belzona 1821 (Fluid Metal)
Belzona 9211 (Supergrip Aggregate)
Belzona 5233

SUBSTRATE
Concrete

APPLICATION METHOD
Areas of concrete were repaired with Belzona 4111. The Belzona 5231 was applied in accordance with System leaflet FPA-8 to the concrete and then the Belzona 1821 and Belzona 9211 grip system was used to create a safety grip system then overcoated with Belzona 5233 for increased UV Stability.

BELZONA FACTS
Belzona was used due to already been applied in other areas of the plant and knowing that Belzona performs very well they opted for Belzona on this particular health and safety issue.

- PICTURES**
1. Application of Belzona 5231
 2. Strips of Belzona 5231
 3. Close up
 4. Final Application Complete



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve