

## BELZONA CHOCKING COMPOUND STABILIZES A LATHE

### CUSTOMER

Malacky, Slovakia

### APPLICATION DATE

2020

### APPLICATION SITUATION

Installed lathe at a machine building manufacturer which required a solid foundation.

### PROBLEM

Lathe required a solution to withstand compressive load of machinery and reduce vibrations.

### PRODUCTS

Belzona 7111 (Industrial Grade)

### SUBSTRATE

Concrete, steel

### APPLICATION METHOD

Belzona System Leaflet GSS-13 was used to set up and apply Belzona 7111 to precisely align the equipment.

### BELZONA FACTS

The Belzona solution secured the equipment for the long-term. Normally the machine would be bolted to the floor, which doesn't prevent corrosion or damage to the baseplate due to vibration.

### PICTURES

1. Installed lathe required a solid foundation
2. Temporary wood dam prepared
3. Pouring Belzona 7111
4. Final Application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2021

  
**BELZONA**  
Repair • Protect • Improve