

PENSTOCK OUTER SURFACE COATED WITH BELZONA

CUSTOMER

Hydro Power Plant, TURKEY

APPLICATION DATE

September 2020

APPLICATION SITUATION

The customer was disturbed by the bad appearance of the swelling of the paint on Penstocks. The material to be selected should be suitable for the moisture during the application.

PROBLEM

The outer surface of the penstock was constantly exposed to moisture. Previously painting swelled in a short time.

PRODUCTS

Belzona 5831 (ST Barrier)

SUBSTRATE

Steel

APPLICATION METHOD

The application was carried out in accordance with belzona System Leaflet TCC-03.

BELZONA FACTS

After a very good surface preparation, although the surface was moist during application, it was a successful application because the selected Belzona product was suitable for this.

PICTURES

1. Before surface preparation, painted surface
2. After grit blasting
3. When applying the second coat of Belzona 5831
4. End of application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve