

PAPER & PULP PLANT TANK REPAIRED WITH BELZONA 5892

CUSTOMER

Poland

APPLICATION DATE

2019

APPLICATION SITUATION

Condensate tank suffering from corrosion.

PROBLEM

Internal of the condensate tank at the paper & pulp plant was suffering from corrosion.

PRODUCTS

Belzona 5892

Belzona 9121

SUBSTRATE

Steel

APPLICATION METHOD

Substrate grit blasted to surface cleanliness (Sa 2 1/2). Followed a profile check for the min surface roughness of 75 microns. Degreasing surfaces with Belzona degreaser 9121 and applied Belzona 5892 in a two coat system. The application was completed in accordance with Belzona System Know-How Leaflet TCC-05.

BELZONA FACTS

Belzona have proven solutions for the paper & pulp industry and used the local distributor for back up service and support.

PICTURES

1. Condensation Tank
2. Application of Belzona 5892
3. Belzona 5892 2nd layer
4. Application Complete



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2020


BELZONA[®]
Repair • Protect • Improve