

## DAIRY FARM WASH STATION PROTECTED WITH BELZONA 4181

### CUSTOMER

Poland

### APPLICATION DATE

2019

### APPLICATION SITUATION

The floor in a wash station of a dairy plant had a number of issues due to the unsealing of joints.

### PROBLEM

Unsealing of the joints in the dairy plant wash station causes floor destruction.

### PRODUCTS

Belzona 4111 (Magma- Quartz)

Belzona 4181 (AHR Magma Quartz)

Belzona 4911

### SUBSTRATE

Concrete

### APPLICATION METHOD

The Application was completed in accordance with Belzona Know-How System Leaflet FPA-01. Removal of damaged concrete and leveling the pump work area. Belzona 4111 applied around the damaged drain area. Belzona 4181 used to provide a chemical resistance to the floor area then post cured by heating the Belzona 4181 for 4 hours.

### BELZONA FACTS

Belzona have an excellent chemical resistant range suitable for application on concrete.

### PICTURES

1. Damaged chemically resistant floors
2. Belzona 4111 around the drain.
3. Application of Belzona 4181
4. Complete Application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2020

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve