

SLIDE ASSEMBLY WITH BELZONA REPAIR

CUSTOMER

Slovakia, metallurgic producer

APPLICATION DATE

2014

APPLICATION SITUATION

Slide assembly were damaged from corrosion.

PROBLEM

Corrosion accelerated due to the inclusion of water and chemicals within the process

PRODUCTS

Belzona 1311

SUBSTRATE

Steel

APPLICATION METHOD


Application was carried out in accordance with modified Belzona Know-How System Leaflet ENC-7.

BELZONA FACTS

Belzona was chosen because welding takes very long time with risk of the compromising the structural integrity.

PICTURES

1. Damaged slide assembly
2. Belzona 1311 application
3. All surface were sanded down
4. Support ready to work



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2020


BELZONA
Repair • Protect • Improve