

BELZONA REPAIRS LEAKING FIRE WATER PIPE LINES OF A NAVY SHIP

CUSTOMER
NAVY

APPLICATION DATE
2019

APPLICATION SITUATION
The fire water pump piping was leaking with no replacement pipe available

PROBLEM
The pipe was leaking causing local flooding in the engine room. The navy tried to seal the leaking pipe with other products, but this had failed & was still leaking. So they contact Belzona

PRODUCTS
Belzona 1212
Belzona 9341 reinforcement tape

SUBSTRATE
Ni, Chromium alloy

APPLICATION METHOD
The application was carried out in accordance with Belzona Know-How system Leaflet VPF 11

BELZONA FACTS
Belzona was the only fast and effective solution to the problem until the new pipe arrive

- PICTURES**
1. Leaking pipe
 2. After surface preparation
 3. Repair in progress
 4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve