

BELZONA REPAIR STRAINERS

CUSTOMER

Namibia

APPLICATION DATE

14 October 2019

APPLICATION SITUATION

Fishing vessel strainers

PROBLEM

Strainers badly eroded

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1321 (Ceramic S-metal)

Belzona 5811 (Immersion grade)

SUBSTRATE

Cast iron

APPLICATION METHOD

Application was carried out according to the Belzona Know-How System Leaflets SOS-1 & SOS-2

BELZONA FACTS

These strainers are very badly damaged and is very costly to repair or manufacture new ones. The only economical way to repair then is with Belzona.

PICTURES

1. Strainer badly corroded
2. Strainer Flange
3. After grid blast
4. Final product done with Belzona 1111 and Belzona 1321, with Belzona 5811 on the outside.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2020


BELZONA[®]
Repair • Protect • Improve