

BELZONA REPAIRS DIESEL ENGINE

CUSTOMER

Croatia

APPLICATION DATE

July 2002

APPLICATION SITUATION

100 cylinders required repairing or would be replaced.

PROBLEM

Pitting corrosion on engine block o-ring seats had caused failure.

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Cast iron

APPLICATION METHOD


The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet ENC-5.

BELZONA FACTS

Customer is the biggest oil company in Croatia and this is an ongoing job since 2002 until today. No replacement was needed in all these years.

PICTURES

1. Damaged area
2. Surface preparation
3. Belzona 1111 rebuild
4. Belzona 1111 machined



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve