

## BELZONA PROVIDES A HARD WEARING GRIP SYSTEM FOR WHISKY BOTTLING PLANT

### CUSTOMER

Glasgow

### APPLICATION DATE

May 2017

### APPLICATION SITUATION

A pallet dispatch yard in a Whisky bottling plant had a health & safety issue caused by poor traction on the concrete floor. During rain showers water would be brought inside the building on forklift truck wheels. This rainwater was causing a slip hazard for both the forklifts & workers in the area. The heavily trafficked area in need of a grip system was over 200 m<sup>2</sup>.

### PROBLEM

A competitor coating system had previously been applied, it was found only to last 6 months in service. The forklift truck wheels produces a particularly harsh grinding effect as they turn. Shut-downs were limited to the weekend only due to tight production schedules.

### PRODUCTS

Belzona 4411 (Granogrip)

Belzona 9231 (Surefoot aggregate)

### SUBSTRATE

Concrete

### APPLICATION METHOD

The application was carried out over two weekends. The area was marked out & prepared with floor grinders. One coat of Belzona 4411 in grey was applied. Belzona 9231 Surefoot aggregate was then used to blind out the area. The area was cured ready to go back into service for the start of production after the weekend.

### BELZONA FACTS

The area has now been in heavy duty service for over 3 years. By utilising the Belzona solution the customer was able to eliminate a health & safety hazard with no disruption to production.

### PICTURES

1. Area in need of grip system
2. Surface preparation
3. Product during application
4. Completed section



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve