

BELZONA PROTECTS TANK FROM EXTERNAL CORROSION

CUSTOMER
South Africa

APPLICATION DATE
2021

APPLICATION SITUATION
A tank required protection from external corrosion at a food production facility.

PROBLEM
External corrosion and chemical attack of the existing coating

PRODUCTS
Belzona 5811 (Immersion grade)

SUBSTRATE
Steel

APPLICATION METHOD
The surface was grit blasted and Belzona 5811 applied per IFU and system leaflet TCC-03

BELZONA FACTS
Belzona 5811 offers cost-effective protection from environmental and chemical attack, which will help extend the lifespan of this piece of equipment

PICTURES

1. Tank prior to surface preparation
2. Tank during surface preparation
3. Tank post surface preparation
4. Completed Application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2021


BELZONA
Repair • Protect • Improve