

BELZONA HELPS PROTECT OFFSHORE PLATFORM LEGS AT WATERLINE

CUSTOMER
Baltic Sea

APPLICATION DATE
Sep-20

APPLICATION SITUATION
Original corrosion protection damaged on platform legs.

PROBLEM
Corrosion of platform legs in the splash zones.

PRODUCTS
Belzona 5831 (ST Barrier)


SUBSTRATE
Steel

APPLICATION METHOD
Application was carried out using a modified version of Belzona Know-How System Leaflet SOS-21. After wet abrasive blasting the Belzona 5831 was applied to the corroded areas above the waterline.

BELZONA FACTS
The surface tolerant properties of Belzona 5831 made it the ideal solution for these difficult access conditions. The product provides excellent adhesion to surfaces both in the splash zone and underwater.

PICTURES

1. Corroded platform legs
2. Surface preparation
3. Belzona 5831 in use.
4. Platform



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com

Copyright © Belzona International Limited 2021


BELZONA[®]
Repair • Protect • Improve