

CHEMICAL CANALIZATION ENTRY REPAIRED WITH BELZONA

CUSTOMER

Petrochemical company, Slovakia

APPLICATION DATE

2016

APPLICATION SITUATION

The concrete was destroyed from chemicals.

PROBLEM

Corrosion of the steel frame and damage to the concrete

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete / Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC 9

BELZONA FACTS

Main benefit for the customer was time, because all repair was carried in very short time, but also important is resistant again chemicals.

PICTURES

1. Chemical canalization entry.
2. Belzona Conditioner application
3. Belzona 4131 application
4. Belzona 5811 in 2 layers

1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2021


BELZONA
Repair • Protect • Improve