

BELZONA PROTECTS NEW BUTYL GLYCOL ESTERS TANKS

CUSTOMER

Lubin, Poland

APPLICATION DATE

Jun-20

APPLICATION SITUATION

Butyl glycol esters tanks needed a protective coating.

PROBLEM

Internal corrosion of tanks damaged due to corrosion and failure of previous coating.

PRODUCTS

Belzona 4311 (Magma CR1)

SUBSTRATE

Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

The client had used a cheap coating in containment area first and after it failed decided to spend a little more money to make it last a long time. Belzona 4311 was applied into the internal lining of the tank and is still in good condition.

PICTURES

1. Asset Location
2. Butyl glycol esters tanks
3. Previous coating corrosion protection damage.
4. Inspection after one year

1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2021


BELZONA[®]
Repair • Protect • Improve