

REPAIR OF DRINKING WATER TANK WITH BELZONA 5811DW2

CUSTOMER
Poland

APPLICATION DATE
Jul-21

APPLICATION SITUATION
Renovation of a Water tank on site using a Belzona Drinking Water approved coating.

PROBLEM
The concrete walls of the water tank had corroded over time leading to deterioration of the substrate subsequently leading to a poorer quality water quality.

PRODUCTS
Belzona 5811DW2
Belzona 4111
Belzona 4911

SUBSTRATE
Concrete

APPLICATION METHOD
The Belzona products were applied in accordance with the Belzona System Leaflet TCC_5.

BELZONA FACTS
Belzona 5811DW2 is a WRAS approved coating for Potable Water, spray applied allowing for a quick and easy return to service.

PICTURES

1. Inside of the Water Tank
2. Re-Build of the Concrete using Belzona 4111
3. Spraying Belzona 5811DW2
4. Completed Application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2021


BELZONA
Repair • Protect • Improve