

BELZONA KEEPS BEET SLICER RUNNING

ID: 10


Industry: *Sugar*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Sugar Beet Mill in North Dakota, U.S.A.*
Application Date: *1983*

Substrate: *Carbon Steel*
Products: ** Belzona® 1111 (Super Metal) ,*

Problem

Bearing failure damaged beet slicer shaft



Photograph Descriptions

- * View of damaged shaft . ,
- * Application of Belzona® 1111 (Super Metal). ,
- * Use of a former to rebuild shaft. ,
- * Completely rebuilt shaft. ,

Application Situation

Beet slicer shaft

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet MPT-2.

Belzona Facts

Repair allowed customer to save time and money by avoiding disassembly of machinery.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve