

BELZONA REPAIR AND PROTECTION OF STABILISER SHAFT

ID: 101

Industry: *General Industry*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Shipping Company, Monaco*
Application Date: *1995*

Substrate: *Steel*
Products: ** Belzona® 1111 (Super Metal) ,*

Problem

Severe pitting corrosion in-board of bearing.



Photograph Descriptions

- * General view of the stabiliser shaft ,
- * After grit blasting, degree of erosion-corrosion damage clearly evident ,
- * Application of Belzona® 1111 being completed ,

Application Situation

Stabilizer shaft

Application Method

Application was carried out in accordance with Belzona System Leaflet SOS-1.

Belzona Facts

Belzona was used because our repair could be done without dismantling.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve