

BELZONA SAVES REFINERY \$50,000

ID: 1013

Industry: Fluid Flow

Customer Location: Refinery - Sweeny, Texas USA

Application: HEX-Heat Exchangers

Application Date: January 2003 and January 2008

Substrate: Carbon Steel

Products: * Belzona® 1111 (Super Metal) ,

* Belzona® 1321 (Ceramic S-Metal) ,

Problem

Galvanic corrosion and erosion resulting in loss of thickness and gasket sealing surfaces. This allows for working fluid to bypass portions of the multi-pass exchanger thereby greatly decreasing the efficiency of the heat exchanger.



Photograph Descriptions

- * Heat exchanger dollar plate prior to repair ,
- * Heat exchanger dollar plate after repair and coating ,
- * Heat exchanger after five years in service ,
- * Heat exchanger channel head after five years in service ,

Application Situation

Multiple heat exchanger components severely damaged by erosion/corrosion.

Application Method

Belzona® 1111 and Belzona® 1321 were applied in accordance with Belzona Know-How System Leaflet HEX-2.

Belzona Facts

Conventional repair involves weld build up followed by the machining of new gasket surfaces at a cost of \$2,500-\$5,000 per dollar plate. The Belzona solution costs less than half of the conventional repair. This results in cost savings of more than \$50,000 per unit turnaround.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

