

BELZONA RAPID FLOOR REPAIR

ID: 1018

Industry: *General Industry*

Customer Location: *Box manufacturer, Montgomery, Alabama USA*

Application: *FPA-Floor Problem Areas*

Application Date: *January 2007*

Substrate: *Concrete*

Products: *Belzona® 4911 (TX Conditioner)<div>Belzona® 4131 (Magma Screed)</div>*

Problem

Hole in floor creating problem for fork lift drivers loading and unloading cardboard for box manufacture.



Photograph Descriptions

* Removed concrete from hole , * Belzona® 4911 being applied , * & 4. Finished application ,

Application Situation

Concrete floor in production area

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

Belzona Facts

The alternative was to saw cut concrete and pour new concrete. That would be more costly because of labor and down time in the area. It was possible to drive over the Belzona applied in morning that night.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve