

BELZONA REPAIR OF CONVEYOR BELT

ID: 1037


Industry: *Power*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Power plant, Bulgaria*
Application Date: *August, 2002*

Substrate: *Rubber*
Products: *Belzona® 2311 (SR Elastomer)*

Problem

Mechanical damage on the protector/scrapper was exposing the metal reinforcement



Photograph Descriptions

* View of the conveyor belt facility , * Conditioning with Belzona® 2911 , * Belzona® 2311 used to rebuild the damage ,

Application Situation

5 km conveyor belt for transporting coal to the power plant

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

Belzona Facts

The customer required the repair with minimum down-time. Belzona was chosen for its effective simple and fast accomplishment without special equipment as per alternative hot vulcanization method.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve