

BELZONA® 4811 REPAIRS TO CONTIMIX HYDROPULPER IN PAPER MILL

ID: 104

Industry: *Pulp & Paper*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Paper Mill in the UK*

Application Date: *1998*

Substrate: *Stainless steel and Basalt*

Products: ** Belzona® 4811 ,*

Problem

Basalt tile lining damaged and efficiency of machine impaired.



Photograph Descriptions

- * View of equipment with lid raised showing the pulping blade ,
- * The area of damaged tiles ,
- * Tiles re-bonded and grouted with Belzona® 4811 ,

Application Situation

Contimix Hydropulper used to shred waste paper.

Application Method

Application was carried out in accordance with Belzona Know-How system SHM-7.

Belzona Facts

Basalt tiles are individually made to size and shape and were not readily available. Repairs with Belzona ensured production was not unduly interrupted. Belzona® 4811 ensured in-fill areas were capable of withstanding the high abrasion similar to the basalt.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve