

OVERNIGHT FLOOR REPAIRS COMPLETED WITH BELZONA


ID: 1051

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: Belzona® 4111 (Magma Quartz)

Customer Location: Dairy, Oklahoma U.S.A.
Application Date: October, 2007

Problem

Floor was eroded and very slippery causing a safety hazard and slowing workers down. There is only an 8 hour window for this repair.



Photograph Descriptions

* Dirty floor , * Surface preparation , * Applying tape & Belzona® 4911 Conditioner , * Squeegee coat of Belzona® 4111 slurry & non-slip applied ,

Application Situation

Floor around the case wash machine.

Application Method

Application was carried out using a modified Belzona Know-How System FPA-1.

After cleaning and grinding floor, pre-warmed Belzona® 4111 mixed as a slurry was applied with a squeegee and surface loaded to rejection with Belzona non-slip aggregate.

Belzona Facts

Belzona cures fast when other products have failed to cure in the time allotted. This repair still looks like new after more than six months.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024