

BELZONA PREVENTS SLIPPING IN WASH AREA

ID: 1053

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: Belzona® 4151 (Magma Resins)

Customer Location: Dairy, Oklahoma USA
Application Date: June, 2006

Problem

Previous applications of non-slip surfacing had peeled so necessitating a more permanent solution.



Photograph Descriptions

* Surface being cleaned , * First coat , * Second coat , * Almost two years later the floor although dirty is 100% intact ,

Application Situation

Walkway in wash station for casings is always wet.

Application Method

Application was carried out using a modified version of Belzona Know-How System FPA-3. after thorough cleaning and abrading, two coats of Belzona® 4151 with a colored aggregate were then applied.

Belzona Facts

This floor is two years old and still in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025