

# BELZONA KEEPS VEHICLES MOVING

ID: 1055

Industry: General Industry

Customer Location: Vehicle Testing Station Bratislava,  
Slovakia

Application: FPA-Floor Problem Areas

Application Date: 2006

Substrate: Floor tiles

Products: \* Belzona® 5811 (Immersion Grade) ,  
\* Belzona® 9211 (Suregrip aggregate) ,

## Problem

During the rain or snow, vehicles were slipping when moving off the brake testing rollers.



## Photograph Descriptions

- \* 1. Vehicle Testing Station ,
- \* 2. Vehicle during the brake testing ,
- \* 3. 2 years in service ,
- \* ,

## Application Situation

Application of grip system to provide better traction on the workshop floor

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona 5811 was applied by brush in a diagonal stripe pattern and blinded with Belzona® 9211.

## Belzona Facts

Customer was looking for quick and “clean” solution. The Belzona solution provided an effective grip system as well as chemical resistance to any spillage or leaks that may occur. The system has proven itself in service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve