

BELZONA IMPROVES CONVEYER EFFICIENCY

ID: 1067

Industry: *General Industry*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Automotive company, Slovakia*



Application Date: *2006*

Substrate: *Rubber*

Products: *Belzona® 2211 (MP Hi-Build Elastomer)*

Problem

Products were sliding on the belt due to incline and smooth surface.



Photograph Descriptions

* Slippery belt , * Application of Belzona® 2211 , * Steel plates for moulding Elastomer to shape , * Completed belt ready to work ,

Application Situation

Elevated conveyer system

Application Method

The application was carried out in accordance with modified Belzona Know-How System Leaflet SHM-5.

Belzona Facts

Customer had problems with sliding of products. To change the belt was expensive. Creating cleats/treads with Belzona was quick, cheap and effective solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve