

# BELZONA IMPROVES CONVEYER EFFICIENCY

ID: 1067

Industry: *General Industry*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Automotive company, Slovakia*

Application Date: *2006*

Substrate: *Rubber*

Products: *Belzona® 2211 (MP Hi-Build Elastomer)*

## Problem

*Products were sliding on the belt due to incline and smooth surface.*



## Photograph Descriptions

\* Slippery belt , \* Application of Belzona® 2211 , \* Steel plates for moulding Elastomer to shape , \* Completed belt ready to work ,

## Application Situation

Elevated conveyer system

## Application Method

The application was carried out in accordance with modified Belzona Know-How System Leaflet SHM-5.

## Belzona Facts

Customer had problems with sliding of products. To change the belt was expensive. Creating cleats/treads with Belzona was quick, cheap and effective solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve