

BELZONA PROTECTS AERATOR IN WATER TREATMENT PLANT

ID: 1081

Industry: Water / Wastewater

Customer Location: Waste Water Treatment Plant, British Columbia

Application: SHM-Solids Handling Machinery


Application Date: November 2007

Substrate: Stainless Steel

Products: Belzona® 1321 (Ceramic S Metal)

Problem

The welded component required protection from bi-metallic corrosion



Photograph Descriptions

* Completed aerator unit in the fabricating shop after grit blasting , * Close up view of the equipment , * Completed application, 2 coats of Belzona® 1321 , * Protected aerator in service ,

Application Situation

Aerator in water treatment process.

Application Method

Application completed in accordance with Belzona Know-How System Leaflet SHM-11.

Belzona Facts

A similar piece of equipment built 6 years previously and protected with Belzona® 1321 had provided extremely good service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve