

BELZONA PROTECTS FILTER FROM SHELLS

ID: 1084

Industry: Power

Customer Location: Nuclear Power Plant, France

Application: TCC-Tanks and Chemical Containment Areas

Application Date: March 2007

Substrate: Mild steel

Products: <div>Belzona® 1111 (Super Metal)</div><div>Belzona® 1321 (Ceramic S Metal)</div>

Problem

Extensive corrosion and deep erosion of metal



Photograph Descriptions

* State of the filter before repairs , * Filter after surface preparation and decontamination , * Filter protected with Belzona® 1321 ,

Application Situation

Sea water filter for cooling water circuit of power plant.

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet TCC-5.

Belzona Facts

The uncoated metal was severely damaged and the efficiency of the system reduced. Belzona solution offered a durable protection against this seawater environment.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve