

BELZONA PROVEN PROTECTION ON TURBINE RUNNER

ID: 1092

Industry: *Power*

Customer Location: *Turbine manufacturer, Italy*

Application: *CEP-Centrifugal Pumps*

Application Date: *May 1987*

Substrate: *Steel*

Products: ** Belzona® EC Barrier ,
* (Belzona® 1321 now recommended) ,*

Problem

Coating protection required to deal with anticipated Erosion and Corrosion.



Photograph Descriptions

- * First coat ,
- * Second Coat applied ,
- * Completed Application ,
- * Coating after 20 years in service ,

Application Situation

Francis Turbine runner for a Hydro Electric Plant in Africa.

Application Method

Surface Preparation and Application was carried out accordance with the relevant IFU and in line with Belzona Know-How System Leaflet CEP-3.

Belzona Facts

The customer contacted the Distributor in September 2007 for a general inspection of the coating which indicated repair was

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA
 Repair • Protect • Improve

needed in areas. A proposal to refurbish with Belzona® 1321 has been made.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

