

# BELZONA GETS TRACTOR BACK ON TRACKS

ID: 1094

Industry: *General Industry*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Agricultural Equipment Suppliers, UK*

Application Date: *March 2008*

Substrate: *Rubber / steel*

Products: *Belzona® 2111 (D&A Hi-Build Elastomer)*

## Problem

*Abrasion of rubber on inside surface of tracks*



## Photograph Descriptions

\* General view of track before repair , \* Close up of damaged area , \* After repair , \* Back on track ,

## Application Situation

Rubber tractor tracks

## Application Method

Application was carried out in accordance with Belzona Know-how System Leaflet SHM-1.

## Belzona Facts

Belzona is the approved repair method by Manufacturer. Whole repair will cost £250. New tracks cost £5500.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2025

  
**BELZONA®**  
Repair • Protect • Improve