

BELZONA GETS TRACTOR BACK ON TRACKS

ID: 1094

Industry: *General Industry*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Agricultural Equipment Suppliers, UK*

Application Date: *March 2008*

Substrate: *Rubber / steel*

Products: *Belzona® 2111 (D&A Hi-Build Elastomer)*

Problem

Abrasion of rubber on inside surface of tracks



Photograph Descriptions

* General view of track before repair , * Close up of damaged area , * After repair , * Back on track ,

Application Situation

Rubber tractor tracks

Application Method

Application was carried out in accordance with Belzona Know-how System Leaflet SHM-1.

Belzona Facts

Belzona is the approved repair method by Manufacturer. Whole repair will cost £250. New tracks cost £5500.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024


BELZONA®
Repair • Protect • Improve