

BELZONA REPAIRS AND PROTECTS ROOF


ID: 1099

Industry: Buildings & Structures
Application: RPA-Roof Problem Areas
Substrate: Steel roof with Aluminium coating
Products: Belzona® 3111 (Flexible Membrane)

Customer Location: Public Gymnasium, France
Application Date: July 2002

Problem

Localised leakage and overall corrosion problem



Photograph Descriptions

* Localised water ingress , * Repair to the seams , * Application extended to cover Corroded roof , * Application completed ,

Application Situation

The building is a public sport facility with a roof surface area of 1400m².

Application Method

Localised repairs carried out in accordance with Belzona Know-How System Leaflet RPA-1. Further corrosion protection achieved by spray application of Belzona® 3111 system.

Belzona Facts

Belzona solution stopped the water ingress into the sports facility and also gives corrosion protection to the overall steel surface.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
Q 09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve