

# BELZONA REPAIRS AND PROTECTS ROOF

ID: 1099

**Industry:** Buildings & Structures  
**Application:** RPA-Roof Problem Areas  
**Substrate:** Steel roof with Aluminium coating  
**Products:** Belzona® 3111 (Flexible Membrane)

**Customer Location:** Public Gymnasium, France  
**Application Date:** July 2002

## Problem

Localised leakage and overall corrosion problem



## Photograph Descriptions

\* Localised water ingress , \* Repair to the seams , \* Application extended to cover Corroded roof , \* Application completed ,

## Application Situation

The building is a public sport facility with a roof surface area of 1400m<sup>2</sup>.

## Application Method

Localised repairs carried out in accordance with Belzona Know-How System Leaflet RPA-1. Further corrosion protection achieved by spray application of Belzona® 3111 system.

## Belzona Facts

Belzona solution stopped the water ingress into the sports facility and also gives corrosion protection to the overall steel surface.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve