

BELZONA PROVIDES SAFE WELCOME

ID: 1100

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Floor tiles
Products: * Belzona® 1321 (Ceramic S Metal) ,

Customer Location: Manufacturer, Slovakia
Application Date: 2008

Problem

During rain or snow people have slip problems on the ramp into the offices.



Photograph Descriptions

- * Ramp entrance ,
- * Templates being placed ,
- * Completed application ,
- ,

Application Situation

Main entrance into companies offices.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona® 1321 was applied by brush in conjunction with Belzona® 9211 (Supergrip Aggregate). Templates were used to create logo.

Belzona Facts

Customer achieved a quick, distinctive and attractive solution. The message reads "welcome to our firm SlovceM".

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve