

# BELZONA EXTENDS RUBBER PUMP LINER LIFE

ID: 1104

Industry: Power  
Application: CEP-Centrifugal Pumps  
Substrate: Rubber  
Products: Belzona® 2121 (D&A Hi-Coat Elastomer)

Customer Location: Power Station, Poland  
Application Date: 2005

## Problem

The rubber liner had limited life (up to 5 years). New liner cost 40,000 EUR



## Photograph Descriptions

\* General view of the pump , \* First coat applied , \* Second coat , \* completed application ,

## Application Situation

Warman pump circulating Gypsum slurry

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3.

## Belzona Facts

New liner costs 40,000 EUR. Belzona coating cost 3,000 EUR and after 3 years in service shows no significant wear.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2024