

BELZONA EXTENDS RUBBER PUMP LINER LIFE

ID: 1104

Industry: Power
Application: CEP-Centrifugal Pumps
Substrate: Rubber
Products: Belzona® 2121 (D&A Hi-Coat Elastomer)

Customer Location: Power Station, Poland
Application Date: 2005

Problem

The rubber liner had limited life (up to 5 years). New liner cost 40,000 EUR



Photograph Descriptions

* General view of the pump , * First coat applied , * Second coat , * completed application ,

Application Situation

Warman pump circulating Gypsum slurry

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3.

Belzona Facts

New liner costs 40,000 EUR. Belzona coating cost 3,000 EUR and after 3 years in service shows no significant wear.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve