

BELZONA TEMPORARY SOLUTION TO A SERIOUS PROBLEM STILL IN SERVICE 10 YEARS LATER

ID: 1106

Industry: *Buildings & Structures*

Customer Location: *Canadian Navy*

Application: *FPA-Floor Problem Areas*

Application Date: *1998*

Substrate: *Rubber & concrete*

Products: *<div>Belzona® 4131 (Magma Screed)</div><div>Belzona® 2131 (D&A Fluid Elastomer)</div><div>Belzona® 4311 (Magma CR1)</div>*

Problem

Chemicals seeping into the ground beneath the facility



Photograph Descriptions

* The cracked membrane was repaired with two coats of Belzona Elastomer , * A pony wall was built using Belzona® 4131 , * The entire rebuilt area was overcoated with two coats of Belzona® 4311 , * View of the repair taken 10 years later showing it to be still in excellent condition ,

Application Situation

Customer had received a violation certificate for cracks in the floor and damage to a rubber membrane beneath a chemical plating facility

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-3, -5 & -6. Rubber membrane was sealed with Elastomer and low retaining wall (pony wall) was constructed.

Belzona Facts

This was an emergency situation because of the high risk hazardous chemicals used in the plating facility. Because of the high degree of compatibility between the Belzona products the various stages of the application could be completed in rapid succession saving many hours of downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

This application, though deemed temporary at the time has been in service for 10 years without the need for any maintenance.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

