

BELZONA SCREED REBUILDS DETERIORATING FLOORS

ID: 1111

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete / Epoxy coating
Products: Belzona® 4131 (Magma Screed)

Customer Location: Supermarket, British Columbia, Canada
Application Date: 2007

Problem

Water trapped beneath the red floor coating was causing odor and health concerns.



Photograph Descriptions

* General view of problem floor showing delamination areas , * Preparation of floor in progress using a Vacu-Grinder , * Application of Belzona® 4131 Magma Screed in progress , * Completed application ,

Application Situation

The original red epoxy coating was delaminating.

Application Method

Application completed in accordance with Belzona Know-How System Leaflet FPA-1. Heat lamps were used to accelerate the cure to ensure area ready for use the following day.

Belzona Facts

Belzona Magma Screed provides hard wearing surface that was applied overnight so causing minimum disruption to the store.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve