

# BELZONA SEALS LOCAL ROOF PROBLEM

ID: 1139

Industry: Military  
Application: RPA-Roof Problem Areas  
Substrate: Bitumen  
Products: \* Belzona® 3111 (Flexible Membrane),

Customer Location: Military Base, Oklahoma  
Application Date: May, 2008

## Problem

Building was being refurbished inside and the roof was leaking in the corner halting the interior work.



## Photograph Descriptions

- \* Leaking section of roof after washing and drying ,
- \* Belzona® 3911 (PSC Conditioner) applied ,
- \* First coat of Belzona® 3111 incorporating reinforcing sheet applied ,
- \* Completed roof repair and leak free ,

## Application Situation

Roof of army base building.

## Application Method

Application was carried out in accordance with Belzona System Leaflets RPA-1,2 & 7. A fully reinforced Belzona® 3111 system was applied to the corner of the roof where leaks were identified.

## Belzona Facts

Repair was done in one day and was leak-free by the next morning when a storm came in. The Belzona system is ideal for localized repair, where its excellent adhesion ensures no peel-back for edges.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve