

BELZONA SEALS LOCAL ROOF PROBLEM

ID: 1139

Industry: Military
Application: RPA-Roof Problem Areas
Substrate: Bitumen
Products: * Belzona® 3111 (Flexible Membrane) ,

Customer Location: Military Base, Oklahoma
Application Date: May, 2008

Problem

Building was being refurbished inside and the roof was leaking in the corner halting the interior work.



Photograph Descriptions

- * Leaking section of roof after washing and drying ,
- * Belzona® 3911 (PSC Conditioner) applied ,
- * First coat of Belzona® 3111 incorporating reinforcing sheet applied ,
- * Completed roof repair and leak free ,

Application Situation

Roof of army base building.

Application Method

Application was carried out in accordance with Belzona System Leaflets RPA-1,2 & 7. A fully reinforced Belzona® 3111 system was applied to the corner of the roof where leaks were identified.

Belzona Facts

Repair was done in one day and was leak-free by the next morning when a storm came in. The Belzona system is ideal for localized repair, where its excellent adhesion ensures no peel-back for edges.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve