

BELZONA REFURBISHES MILITARY DOG KENNELS

ID: 1142

Industry: *Buildings & Structures*

Application: *FPA-Floor Problem Areas*

Substrate: *Concrete and Cinder Block*


Products: *Belzona® 4111 (Magma Quartz)<div>Belzona® 5111 (Ceramic Cladding)</div><div>Belzona® 5811 (Immersion Grade)</div>*

Customer Location: *Military Base, North Alabama*

Application Date: *April 2006*

Problem

An easy to clean, hygienic non slip coating required.



Photograph Descriptions

* Prepped and ready to coat , * Floor and coves covered , * Almost complete, walls being coated , * All done! Ready to turn over to the owners ,

Application Situation

Floors and walls in dog kennels.

Application Method

This application was performed in accordance with Belzona Know-How System Leaflets FPA-3 & TCC-15.

To create a non-slip surface that did not damage paws, different aggregates were tried before settling on a non-standard Belzona one that was found to be ideal. Coves between wall and floor were formed and Belzona® 5111 provided stain resistant finish.

Belzona Facts

The Commander tried many different coatings over the years and had not found a suitable coating that stood up to the wear and tear of the dogs. Our Belzona application has been down for 2 years and looks just like new.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve