

# BELZONA SEALS UPPER FLOOR PUMP ROOM


ID: 1145

Industry: *Buildings & Structures*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Concrete*  
Products: *Belzona® 5811 (Immersion Grade)*

Customer Location: *County Hospital, Colton California U.S.A.*  
Application Date: *2007*

## Problem

*Copper pipes leaking water on the floor was leaking through the concrete to the lower level.*



## Photograph Descriptions

\* The pump room showing the pipes that keep leaking , \* Reinforcement tape used for edges , \* Back of pump room , \* Finished floor ,

## Application Situation

Pump room at hospital positioned on floor above computer room.

## Application Method

Application was carried out using a modified Belzona Know-How System TCC-15.

After washing and removing dirt from floor Belzona® 5811 was used to coat the entire floor plus 6 inches up the wall to completely encapsulate the area and to form a containment area.

## Belzona Facts

This application saved the hospital tens of thousands of dollars due to the last time the floor leaked it ruined all of the PCs below.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve