

# OLD APPLICATION MEETS NEW BELZONA APPLICATION

ID: 1174

Industry: Buildings & Structures

Customer Location: Railroad in Saint Paul, Minnesota U.S.A.

Application: FPA-Floor Problem Areas

Application Date: 1996 and 2008

Substrate: Concrete

Products: \* Belzona® 4411 (Granogrip),  
\* Belzona® 5231 (SG Laminate),

## Problem

The floor gets covered in fuel and water causing a slip hazard. Also the cleaning method began attacking the concrete.



## Photograph Descriptions

- \* Preparing the surface ,
- \* Taping off edges ,
- \* Patching holes before coating ,
- \* Old Belzona® 4411 on ramps meets new Belzona® 5231 on workshop floor ,

## Application Situation

Diesel shop floor and ramps

## Application Method

Applications was carried out in accordance with Belzona Know-How System Leaflets FPA-3 & FPA-8.

## Belzona Facts

The ramps where done over 12 years ago and still in great condition saving time and money spent re-doing them repeatedly with systems. The floor has shown to be a safety benefit that also is easier and faster for crews to clean.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

