

BELZONA SEALS PACKING FACILITY


ID: 1175

Industry: *General Industry*
Application: *RPA-Roof Problem Areas*
Substrate: *Aluminum*
Products: *Belzona® 3111 (Flexible Membrane)*

Customer Location: *Cement Company, Miami, Florida U.S.A.*
Application Date: *April 2008*

Problem

Roof was leaking through the seams and joints.



Photograph Descriptions

* Uncoated seams , * Belzona® 3921 (GSC Conditioner) being applied , * Seams being coated with Belzona® 3111 and reinforced with Belzona® 9311 , * Finished application. ,

Application Situation

Bolted metal roof

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

Belzona Facts

The customer was previously using a low cost silicone sealant with poor results allowing continued damage to expensive packing machinery and controls.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve