

BELZONA KEEPS AIRPORT SAFE FOR TRAVELLERS

ID: 1196

Industry: Buildings & Structures

Customer Location: Airport, Alabama U.S.A.

Application: FPA-Floor Problem Areas

Application Date: 2000

Substrate: Concrete

Products: * Belzona® 2221 (MP Fluid Elastomer),

Problem

Old sealant was coming out of the joints. Steel plates over the joints did not alleviate the safety concerns.



Photograph Descriptions

- * The passenger terminal ,
- * One of the application areas ,
- * Problem joint in front of escalator ,
- * Completed Belzona® 2221 application ,

Application Situation

Expansion joints in passenger terminal.

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet FPA-6.

Belzona Facts

Joints still in service after 8 years. Excellent adhesion ensures no trip hazard created by failed sealant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA
 Repair • Protect • Improve