

BELZONA SOLVES PROBLEM WITH AGITATOR BLADES

ID: 120

Industry: *Sugar*
Application: *FBC-Fans, Blowers and Compressors*

Customer Location: *Sugar Beet Mill in Italy*
Application Date: *1992*

Substrate: *Steel*
Products: ** Belzona® 1311 (Ceramic R-Metal) ,*
** Belzona® 1321 (Ceramic S-Metal) ,*
** Belzona® 2121 (D&A Hi-Coat Elastomer) ,*

Problem

Abrasive solids in settling tank caused erosion on the surface of the agitator blades.



Photograph Descriptions

- * Damaged base of agitator. ,
- * Blades rebuilt with Belzona® 1000 Series product. ,
- * Application of Belzona® 2000 Series product. ,

Application Situation

Agitator in settling tank of wastewater treatment station in a sugar beet mill

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet FBC-1.

Belzona Facts

When damage is due primarily to abrasion, the recommended solution is to rebuild and coat with the Belzona® Ceramic Metal System respectively. The Belzona® 2000 Series Elastomeric Polymers also may be used when impact and abrasion are the contributing factors.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

