

BELZONA PROTECTS 98% SULFURIC ACID CONTAINMENT AREA


ID: 1207

Industry: Power
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Concrete
Products: Belzona® 4311 (Magma CR1)

Customer Location: Power Plant, Alabama USA
Application Date: December 2007

Problem

Sulfuric Acid containment area coating had failed and needed re-coating.



Photograph Descriptions

* Old coating being removed , * Belzona® 4311 being applied , * & 4. Completed application ,

Application Situation

98% Sulfuric Acid containment area in water treatment plant.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Old coating was removed using high pressure water blasting. Belzona® 4311 was applied to both containment and tank stands.

Belzona Facts

Belzona has been used for years in many of Alabama Powers plants. Customer trusted product and longevity of previous applications.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve